

Structural Investigation and Design - Case Study

Cleveland Potash Quay Repairs

Ian Farmer Associates carried out an investigation and testing works on a quay structure to ascertain the condition of the structure and to enable the design of subsequent repair works to be carried out to the quay.



The company carried out a strategic design of the repairs to the quay to both maintain integrity of the quay during the repair phase and to allow continued operation in the future.

It was essential that operational capacity of the quay was maintained during the contract and as such, IFA carried out design engineer duties to ensure a fast response to all technical site queries. IFA also worked closely with the Project Manager and the client to ensure the works were carried out under the required quality regime.

Client Comments:

“From tender to completion, Ian Farmer Associates have exceeded our high expectations, ensuring the repairs of the Quay were completed to specification and design. Cleveland Potash would most certainly recommended their services and would not hesitate to use them again in the future.”

Don Huddleston, Manager, Cleveland Potash Limited

Ian Farmer Associates
www.ianfarmerassociates.co.uk

